





AVX Corporation


CP0402A1810CNTR

| | |
|-----------------------|---|
| Nambari ya Sehemu: | CP0402A1810CNTR |
| Mtengenezaji / Brand: | AVX Corporation |
| Maelezo ya bidhaa | RF DIR COUPLER 1.81GHZ 0402 |
| Datasheets: |  CP0402A1810CNTR.pdf |
| Hali ya RoHs |  Kuongoza bure / RoHS Inavyotakiwa |
| Hali | 502613 pcs stock |
| Meli Kutoka | Hong Kong |
| Njia ya Uhamisho | DHL/Fedex/TNT/UPS/EMS |

[OMBI LA NUKUU](#)

Picha inaweza kuwa uwakilishi. Angalia maelezo ya maelezo ya bidhaa.













Ufafanuzi wa CP0402A1810CNTR

| | |
|--|---|
| NAMBARI YA SEHEMU | CP0402A1810CNTR |
| MTENGENEZAJI | AVX Corporation |
| MAELEZO | RF DIR COUPLER 1.81GHZ 0402 |
| HALI YA BURE YA BURE / HALI YA ROHS | Kuongoza bure / RoHS Inavyotakiwa |
| KIASI INAPATIKANA | 502613 pcs |
| KARATASI YA DATA |  CP0402A1810CNTR.pdf |
| DUKA LA KIFAA CHA WASAMBAZAJI | 0402 |
| MFULULIZO | - |
| KURUDI KUPOTEZA | - |
| NGUVU - MAX | 3W |
| UFUNGAJI | Tape & Reel (TR) |
| PAKET / UCHUNGUZI | 0402 (1005 Metric) |
| KIWANGO CHA SENSITIVITY MOISTURE (MSL) | 1 (Unlimited) |
| HALI YA BURE YA BURE / HALI YA ROHS | Lead free / RoHS Compliant |
| KUTENGWA | - |
| KUPOTEZA KURINGIZWA | - |
| UPEPO | 1.81GHz |
| MAELEZO YA KINA | RF Directional Coupler 1.81GHz 3W 0402 (1005 Metric) |
| KIPENGEE CHA KUUNGANISHA | - |
| AINA YA NDOA | Standard |
| MAOMBI | - |

Tags kuhusiana

| | | |
|----------------------------------|---------------------------------------|---------------------------------------|
| AVX Corporation CP0402A1810CNTR | Mgawanyiko wa CP0402A1810CNTR | Mtoa CP0402A1810CNTR |
| CP0402A1810CNTR Bei | CP0402A1810CNTR Picha | CP0402A1810CNTR Image |
| Datasheet ya CP0402A1810CNTR PDF | CP0402A1810CNTR Pakua Datasheet | Datasheet ya CP0402A1810CNTR |
| CP0402A1810CNTR Stock | Nunua CP0402A1810CNTR | Nunua AVX Corporation CP0402A1810CNTR |
| AVX Corporation CP0402A1810CNTR | Mtoa AVX Corporation | Mgawanyiko wa AVX Corporation |
| AVX Corporation CP0402A1810CNTR | AVX Corporation [MIL] CP0402A1810CNTR | |

Bidhaa zinazohusiana

| | |
|--|--|
|  <p>CP0402A1880ALTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 409591 pcs</p> <p>RFQ</p> |  <p>CP0402A1842DLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.805-1.88GHZ 0402 Katika hisa: 450583 pcs</p> <p>RFQ</p> |
|  <p>CP0402A1880BNTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 436936 pcs</p> <p>RFQ</p> |  <p>CP0402A0942DLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 925-960MHZ 0402 Katika hisa: 487613 pcs</p> <p>RFQ</p> |
|  <p>CP0402A1880BLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 429093 pcs</p> <p>RFQ</p> |  <p>CP0402A1880ANTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 393543 pcs</p> <p>RFQ</p> |
|  <p>CP0402A1842ALTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.805-1.88GHZ 0402 Katika hisa: 509192 pcs</p> <p>RFQ</p> |  <p>CP0402A0942BLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 925-960MHZ 0402 Katika hisa: 462199 pcs</p> <p>RFQ</p> |
|  <p>CP0402A1441ALTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.429-1.453GHZ 0402 Katika hisa: 502227 pcs</p> <p>RFQ</p> |  <p>CP0402A0947FLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 925-960MHZ 0402 Katika hisa: 441222 pcs</p> <p>RFQ</p> |
|  <p>CP0402A1810BNTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.81GHZ 0402 Katika hisa: 513040 pcs</p> <p>RFQ</p> |  <p>CP0402A0942ALTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 925-960MHZ 0402 Katika hisa: 435818 pcs</p> <p>RFQ</p> |