



TDK Corporation

HHM1918A2

Nambari ya Sehemu:	HHM1918A2
Mtengenezaji / Brand:	TDK Corporation
Maelezo ya bidhaa	BALUN 2.3GHZ-2.7GHZ 50/100 0402
Datasheets:	HHM1918A2.pdf
Hali ya RoHs	Kuongoza bure / RoHS Inavyotakiwa
Hali	1190924 pcs stock
Meli Kutoka	Hong Kong
Njia ya Uhamisho	DHL/Fedex/TNT/UPS/EMS

OMBI LA NUKUU

Picha inaweza kuwa uwakilishi. Angalia maelezo ya maelezo ya bidhaa.

Ufafanuzi wa HHM1918A2

NAMBARI YA SEHEMU	HHM1918A2
MTENGENEZAJI	TDK Corporation
MAELEZO	BALUN 2.3GHZ-2.7GHZ 50/100 0402
HALI YA BURE YA BURE / HALI YA ROHS	Kuongoza bure / RoHS Inavyotakiwa
KIASI INAPATIKANA	1190924 pcs
KARATASI YA DATA	HHM1918A2.pdf
MFULULIZO	HHM
KURUDI KUPOTEZA (MIN)	10dB
TOFAUTI YA AWAMU	180° ±15°
UFUNGAJI	Tape & Reel (TR)
PAKET / UCHUNGUZI	0402 (1005 Metric)
MAJINA MENGINE	445-175601-2
AINA YA KUINUA	Surface Mount
KIWANGO CHA SENSITIVITY MOISTURE (MSL)	1 (Unlimited)
HALI YA BURE YA BURE / HALI YA ROHS	Lead free / RoHS Compliant
UPUNGUFU WA KUIINGIZA (MAX)	0.8dB
IMPEDANCE - UNBALANCED / BALANCED	50 / 100 Ohm
MZUNGUKO WA MZUNGUKO	2.3GHz ~ 2.7GHz
MAELEZO YA KINA	RF Balun 2.3GHz ~ 2.7GHz 50 / 100 Ohm 0402 (1005 Metric)

Tags kuhusiana

TDK Corporation HHM1918A2	Mgawanyiko wa HHM1918A2	Mtoa HHM1918A2
HHM1918A2 Bei	HHM1918A2 Picha	HHM1918A2 Image
Datasheet ya HHM1918A2 PDF	HHM1918A2 Pakua Datasheet	Datasheet ya HHM1918A2
HHM1918A2 Stock	Nunua HHM1918A2	Nunua TDK Corporation HHM1918A2
TDK Corporation HHM1918A2	Mtoa TDK Corporation	Mgawanyiko wa TDK Corporation
TDK Corporation HHM1918A2		

Bidhaa zinazohusiana

<p>HHM1932A2 Wazalishaji: TDK Corporation Maelezo: BALUN 862MHZ-894MHZ 50/100 0402 Katika hisa: 1054239 pcs</p> <p>RFQ</p>	<p>HHM1904C1 Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/75 0402 Katika hisa: 47142 pcs</p> <p>RFQ</p>
<p>HHM1927A4 Wazalishaji: TDK Corporation Maelezo: BALUN 1.805-2.17GHZ 50/100 0402 Katika hisa: 319228 pcs</p> <p>RFQ</p>	<p>HHM1906A1 Wazalishaji: TDK Corporation Maelezo: BALUN 4.9GHZ-5.95GHZ 50/75 0402 Katika hisa: 3696 pcs</p> <p>RFQ</p>
<p>HHM2202SA2 Wazalishaji: TDK Corporation Maelezo: RF DIR COUPLER 1.71-1.79GHZ 0603 Katika hisa: 4048 pcs</p> <p>RFQ</p>	<p>HHM1917A5 Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/50 0402 Katika hisa: 335006 pcs</p> <p>RFQ</p>
<p>HHM1904A1 Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/75 0402 Katika hisa: 58057 pcs</p> <p>RFQ</p>	<p>HHM22106C1 Wazalishaji: TDK Corporation Maelezo: RF DIR CPLR 700MHZ-2.7GHZ 0603 Katika hisa: 1052355 pcs</p> <p>RFQ</p>
<p>HHM1907B1 Wazalishaji: TDK Corporation Maelezo: BALUN 4.9GHZ-5.95GHZ 50/50 0402 Katika hisa: 307944 pcs</p> <p>RFQ</p>	<p>HHM1903A4 Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/100 0402 Katika hisa: 314972 pcs</p> <p>RFQ</p>
<p>HHM2204SA1 Wazalishaji: TDK Corporation Maelezo: RF DIR COUPLR 1.71-1.785GHZ 0603 Katika hisa: 237035 pcs</p> <p>RFQ</p>	<p>HHM1946A1 Wazalishaji: TDK Corporation Maelezo: BALUN 2.3GHZ-2.7GHZ 50/100 0402 Katika hisa: 62622 pcs</p> <p>RFQ</p>

