




Aeroflex (MACOM Technology Solutions)

## MACP-011014

Nambari ya Sehemu:	MACP-011014
Mtengenezaji / Brand:	Aeroflex (MACOM Technology Solutions)
Maelezo ya bidhaa	RF DIR COUPLER 5MHZ-1.5GHZ 6SMD
Datasheets:	MACP-011014.pdf
Hali ya RoHS	Kuongoza bure / RoHS Inavyotakiwa
Hali	34558 pcs stock
Meli Kutoka	Hong Kong
Njia ya Uhamisho	DHL/Fedex/TNT/UPS/EMS

**OMBI LA NUKUU**

### Solutions



Picha inaweza kuwa uwakilishi. Angalia maelezo ya maelezo ya bidhaa.

### Ufafanuzi wa MACP-011014

NAMBARI YA SEHEMU	MACP-011014
MTENGENEZAJI	Aeroflex (MACOM Technology Solutions)
MAELEZO	RF DIR COUPLER 5MHZ-1.5GHZ 6SMD
HALI YA BURE YA BURE / HALI YA ROHS	Kuongoza bure / RoHS Inavyotakiwa
KIASI INAPATIKANA	34558 pcs
KARATASI YA DATA	MACP-011014.pdf
DUKA LA KIFAA CHA WASAMBAZAJI	6-SMD
MFULULIZO	-
KURUDI KUPOTEZA	22dB
NGUVU - MAX	500mW
UFUNGAJI	Original-Reel®
PAKET / UCHUNGUZI	6-SMD Module, No Lead
MAJINA MENGINE	1465-1716-6
KIWANGO CHA SENSITIVITY MOISTURE (MSL)	1 (Unlimited)
HALI YA BURE YA BURE / HALI YA ROHS	Lead free / RoHS Compliant
KUTENGWA	27dB
KUPOTEZA KUIINGIZWA	0.93dB
UPEPO	5MHz ~ 1.5GHz
MAELEZO YA KINA	RF Directional Coupler General Purpose 5MHz ~ 1.5GHz 500mW 6-SMD Module, No Lead
KIPENGEE CHA KUUNGANISHA	-
AINA YA NDOA	Standard
MAOMBI	General Purpose

### Tags kuhusiana

Aeroflex (MACOM Technology Solutions) MACP-011014	Mgawanyiko wa MACP-011014	Mtoa MACP-011014
MACP-011014 Bei	MACP-011014 Picha	MACP-011014 Image
Datasheet ya MACP-011014 PDF	MACP-011014 Pakua Datasheet	Datasheet ya MACP-011014
MACP-011014 Stock	Nunua MACP-011014	Nunua Aeroflex (MACOM Technology Solutions) MACP-011014
Aeroflex (MACOM Technology Solutions) MACP-011014	Mtoa Aeroflex (MACOM Technology Solutions)	Mgawanyiko wa Aeroflex (MACOM Technology Solutions)
Aeroflex (MACOM Technology Solutions) MACP-011014	Aeroflex Circuit Technology MACP-011014	Aeroflex MACP-011014
Aeroflex (MACOM Technology Solutions) MACP-011014	Aeroflex Metelics, Division of MACOM MACP-011014	M/A-Com Technology Solutions MACP-011014
Metelics (MACOM Technology Solutions) MACP-011014	MACOM Technology Solutions MACP-011014	

### Bidhaa zinazohusiana

<p><b>MACP-011032</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Katika hisa: 33983 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-010563-000000</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 10GHZ-30GHZ 6TDFN Katika hisa: 6556 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011010</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Katika hisa: 69745 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011033</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Katika hisa: 34032 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011036</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Katika hisa: 4034 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011013</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD Katika hisa: 75305 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-010563-TR1000</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 10GHZ-30GHZ 6TDFN Katika hisa: 4446 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-010562-TR1000</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 6GHZ-18GHZ 6TDFN Katika hisa: 3016 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011015</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD Katika hisa: 24969 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011034</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Katika hisa: 34659 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011035</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Katika hisa: 31816 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-010563-001SMB</b> Wazalishaji: Aeroflex (MACOM Technology Solutions) Maelezo: EVAL BOARD FOR MACP-010563-TR100 Katika hisa: 4608 pcs</p> <p><b>RFQ</b></p>

