



AVX Corporation


CP0805A1880BWTR

Nambari ya Sehemu:	CP0805A1880BWTR
Mtengenezaji / Brand:	AVX Corporation
Maelezo ya bidhaa	RF DIR COUPLER 1.85-1.91GHZ 0805
Datasheets:	 CP0805A1880BWTR.pdf
Hali ya RoHs	 Ina lead / RoHS isiyo ya kuzingatia
Hali	282423 pcs stock
Meli Kutoka	Hong Kong
Njia ya Uhamisho	DHL/Fedex/TNT/UPS/EMS

[OMBI LA NUKUU](#)

Picha inaweza kuwa uwakilishi. Angalia maelezo ya maelezo ya bidhaa.













Ufafanuzi wa CP0805A1880BWTR

NAMBARI YA SEHEMU	CP0805A1880BWTR
MTENGENEZAJI	AVX Corporation
MAELEZO	RF DIR COUPLER 1.85-1.91GHZ 0805
HALI YA BURE YA BURE / HALI YA ROHS	Ina lead / RoHS isiyo ya kuzingatia
KIASI INAPATIKANA	282423 pcs
KARATASI YA DATA	 CP0805A1880BWTR.pdf
DUKA LA KIFAA CHA WASAMBAZAJI	0805
MFULULIZO	-
KURUDI KUPOTEZA	-29dB
NGUVU - MAX	3W
UFUNGAJI	Tape & Reel (TR)
PAKET / UCHUNGUZI	0805 (2012 Metric)
KIWANGO CHA SENSITIVITY MOISTURE (MSL)	1 (Unlimited)
HALI YA BURE YA BURE / HALI YA ROHS	Contains lead / RoHS non-compliant
KUTENGWA	-22dB
KUPOTEZA KUINGIZWA	0.6dB
UPEPO	1.85GHz ~ 1.91GHz
MAELEZO YA KINA	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 12 ± 1dB 3W 0805 (2012 Metric)
KIPENGEE CHA KUUNGANISHA	12 ± 1dB
AINA YA NDOA	Standard
MAOMBI	PCS

Tags kuhusiana

AVX Corporation CP0805A1880BWTR	Mgawanyiko wa CP0805A1880BWTR	Mtoa CP0805A1880BWTR
CP0805A1880BWTR Bei	CP0805A1880BWTR Picha	CP0805A1880BWTR Image
Datasheet ya CP0805A1880BWTR PDF	CP0805A1880BWTR Pakua Datasheet	Datasheet ya CP0805A1880BWTR
CP0805A1880BWTR Stock	Nunua CP0805A1880BWTR	Nunua AVX Corporation CP0805A1880BWTR
AVX Corporation CP0805A1880BWTR	Mtoa AVX Corporation	Mgawanyiko wa AVX Corporation
AVX Corporation CP0805A1880BWTR	AVX Corporation [MIL] CP0805A1880BWTR	

Bidhaa zinazohusiana

 <p>CP0805A1907AWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.895-1.92GHZ 0805 Katika hisa: 234814 pcs</p> <p>RFQ</p>	 <p>CP0805A1842AWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.805-1.88GHZ 0805 Katika hisa: 291374 pcs</p> <p>RFQ</p>
 <p>CP0805A1960AWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.93-1.99GHZ 0805 Katika hisa: 199692 pcs</p> <p>RFQ</p>	 <p>CP0805A1747DWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.71-1.785GHZ 0805 Katika hisa: 290903 pcs</p> <p>RFQ</p>
 <p>CP0805A1890BWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.88-1.9GHZ 0805 Katika hisa: 276537 pcs</p> <p>RFQ</p>	 <p>CP0805A1890BWTR\500 Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.88-1.9GHZ 0805 Katika hisa: 251680 pcs</p> <p>RFQ</p>
 <p>CP0805A1880CWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0805 Katika hisa: 261094 pcs</p> <p>RFQ</p>	 <p>CP0805A1747AWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.71-1.785GHZ 0805 Katika hisa: 282291 pcs</p> <p>RFQ</p>
 <p>CP0805A1747CWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.71-1.785GHZ 0805 Katika hisa: 299089 pcs</p> <p>RFQ</p>	 <p>CP0805A1720BWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.72GHZ 0805 Katika hisa: 257960 pcs</p> <p>RFQ</p>
 <p>CP0805A1880EWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0805 Katika hisa: 279177 pcs</p> <p>RFQ</p>	 <p>CP0805A1880AWTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0805 Katika hisa: 309114 pcs</p> <p>RFQ</p>