





AVX Corporation


CP0402A1950ALTR

Nambari ya Sehemu:	CP0402A1950ALTR
Mtengenezaji / Brand:	AVX Corporation
Maelezo ya bidhaa	RF DIR COUPLER 1.9GHZ 0402
Datasheets:	 CP0402A1950ALTR.pdf
Hali ya RoHs	 Kuongoza bure / RoHS Inavyotakiwa
Hali	414676 pcs stock
Meli Kutoka	Hong Kong
Njia ya Uhamisho	DHL/Fedex/TNT/UPS/EMS

[OMBI LA NUKUU](#)

Picha inaweza kuwa uwakilishi. Angalia maelezo ya maelezo ya bidhaa.













Ufafanuzi wa CP0402A1950ALTR

NAMBARI YA SEHEMU	CP0402A1950ALTR
MTENGENEZAJI	AVX Corporation
MAELEZO	RF DIR COUPLER 1.9GHZ 0402
HALI YA BURE YA BURE / HALI YA ROHS	Kuongoza bure / RoHS Inavyotakiwa
KIASI INAPATIKANA	414676 pcs
KARATASI YA DATA	 CP0402A1950ALTR.pdf
DUKA LA KIFAA CHA WASAMBAZAJI	0402
MFULULIZO	-
KURUDI KUPOTEZA	-
NGUVU - MAX	3W
UFUNGAJI	Tape & Reel (TR)
PAKET / UCHUNGUZI	0402 (1005 Metric)
MAJINA MENGINE	CP0402A1950AL CP0402A1950AL-ND
KIWANGO CHA SENSITIVITY MOISTURE (MSL)	1 (Unlimited)
HALI YA BURE YA BURE / HALI YA ROHS	Lead free / RoHS Compliant
KUTENGWA	-
KUPOTEZA KUIINGIZWA	-
UPEPO	1.9GHz
MAELEZO YA KINA	RF Directional Coupler 1.9GHz 3W 0402 (1005 Metric)
KIPENGEE CHA KUUNGANISHA	-
AINA YA NDOA	Standard
MAOMBI	-

Tags kuhusiana

AVX Corporation CP0402A1950ALTR	Mgawanyiko wa CP0402A1950ALTR	Mtoa CP0402A1950ALTR
CP0402A1950ALTR Bei	CP0402A1950ALTR Picha	CP0402A1950ALTR Image
Datasheet ya CP0402A1950ALTR PDF	CP0402A1950ALTR Pakua Datasheet	Datasheet ya CP0402A1950ALTR
CP0402A1950ALTR Stock	Nunua CP0402A1950ALTR	Nunua AVX Corporation CP0402A1950ALTR
AVX Corporation CP0402A1950ALTR	Mtoa AVX Corporation	Mgawanyiko wa AVX Corporation
AVX Corporation CP0402A1950ALTR	AVX Corporation [MIL] CP0402A1950ALTR	

Bidhaa zinazohusiana

 <p>CP0402A1950CLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.9GHZ 0402 Katika hisa: 486772 pcs</p> <p>RFQ</p>	 <p>CP0402A1880ENTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 479821 pcs</p> <p>RFQ</p>
 <p>CP0402A1950ELTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.9GHZ 0402 Katika hisa: 392608 pcs</p> <p>RFQ</p>	 <p>CP0402A1890ALTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.88-1.9GHZ 0402 Katika hisa: 502970 pcs</p> <p>RFQ</p>
 <p>CP0402A1950FLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.9GHZ 0402 Katika hisa: 464652 pcs</p> <p>RFQ</p>	 <p>CP0402A1880ELTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 415023 pcs</p> <p>RFQ</p>
 <p>CP0402A1960ALTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.93-1.99GHZ 0402 Katika hisa: 433792 pcs</p> <p>RFQ</p>	 <p>CP0402A1950BLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.9GHZ 0402 Katika hisa: 487993 pcs</p> <p>RFQ</p>
 <p>CP0402A1950DLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.9GHZ 0402 Katika hisa: 474253 pcs</p> <p>RFQ</p>	 <p>CP0402A1880DNTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 435221 pcs</p> <p>RFQ</p>
 <p>CP0402A1890ELTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.88-1.9GHZ 0402 Katika hisa: 459521 pcs</p> <p>RFQ</p>	 <p>CP0402A1880DLTR Wazalishaji: AVX Corporation Maelezo: RF DIR COUPLER 1.85-1.91GHZ 0402 Katika hisa: 459126 pcs</p> <p>RFQ</p>