



TDK Corporation

## HHM1711Q1

Nambari ya Sehemu:	HHM1711Q1
Mtengenezaji / Brand:	TDK Corporation
Maelezo ya bidhaa	BALUN 2.3GHZ-3.8GHZ 50/100 0603
Datasheets:	<a href="#">HHM1711Q1.pdf</a>
Hali ya RoHs	Kuongoza bure / RoHS Inavyotakiwa
Hali	836875 pcs stock
Meli Kutoka	Hong Kong
Njia ya Uhamisho	DHL/Fedex/TNT/UPS/EMS

**OMBI LA NUKUU**

Picha inaweza kuwa uwakilishi. Angalia maelezo ya maelezo ya bidhaa.

### Ufafanuzi wa HHM1711Q1

NAMBARI YA SEHEMU	HHM1711Q1
MTENGENEZAJI	TDK Corporation
MAELEZO	BALUN 2.3GHZ-3.8GHZ 50/100 0603
HALI YA BURE YA BURE / HALI YA ROHS	Kuongoza bure / RoHS Inavyotakiwa
KIASI INAPATIKANA	836875 pcs
KARATASI YA DATA	<a href="#">HHM1711Q1.pdf</a>
MFULULIZO	HHM
KURUDI KUPOTEZA (MIN)	10dB
TOFAUTI YA AWAMU	180° ±15°
UFUNGAJI	Tape & Reel (TR)
PAKET / UCHUNGUZI	0603 (1608 Metric), 6 PC Pad
MAJINA MENGINE	445-175592-2 HHM1711Q1-ND Q10431685
AINA YA KUINUA	Surface Mount
KIWANGO CHA SENSITIVITY MOISTURE (MSL)	1 (Unlimited)
HALI YA BURE YA BURE / HALI YA ROHS	Lead free / RoHS Compliant
UPUNGUFU WA KUINGIZA (MAX)	1dB
IMPEDANCE - UNBALANCED / BALANCED	50 / 100 Ohm
MZUNGUKO WA MZUNGUKO	2.3GHz ~ 3.8GHz
MAELEZO YA KINA	RF Balun 2.3GHz ~ 3.8GHz 50 / 100 Ohm 0603 (1608 Metric), 6 PC Pad

### Tags kuhusiana

TDK Corporation HHM1711Q1	Mgawanyiko wa HHM1711Q1	Mtoa HHM1711Q1
HHM1711Q1 Bei	HHM1711Q1 Picha	HHM1711Q1 Image
Datasheet ya HHM1711Q1 PDF	HHM1711Q1 Pakua Datasheet	Datasheet ya HHM1711Q1
HHM1711Q1 Stock	Nunua HHM1711Q1	Nunua TDK Corporation HHM1711Q1
TDK Corporation HHM1711Q1	Mtoa TDK Corporation	Mgawanyiko wa TDK Corporation
TDK Corporation HHM1711Q1		

### Bidhaa zinazohusiana

<p><b>HHM17144A1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 791MHZ-960MHZ 50/100 0603 Katika hisa: 862583 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17139B2</b> Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.6GHZ 50/50 0603 Katika hisa: 823244 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1596A1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 3.1GHZ-4.9GHZ 50/100 0805 Katika hisa: 493437 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17152A1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 698MHZ-894MHZ 50/100 0603 Katika hisa: 506941 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1711D1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Katika hisa: 180690 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17146A1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 1.92GHZ-2.17GHZ 50/50 0603 Katika hisa: 920864 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1603A1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD Katika hisa: 120843 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1710D1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Katika hisa: 460907 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17125D1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Katika hisa: 496156 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1711E1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Katika hisa: 796296 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17139B1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Katika hisa: 255709 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1595A1</b> Wazalishaji: TDK Corporation Maelezo: BALUN 3GHZ-8GHZ 50/100 0805 Katika hisa: 163352 pcs</p> <p><b>RFQ</b></p>

